

On the premises of PCC Group, Brzeg Dolny, observe the following restrictions and limitations:



Do not enter off-limits zones, that is manufacturing or warehouse stations, if not authorised to



Do not smoke tobacco outside of designated smoking areas



Bringing or using alcohol and other psychoactive substances or being under their influence is strictly prohibited



Photographing and filming is allowed only having obtained a written authorisation



On the premises of the entire plant, there is a speed limit, up to 30 km/h; also, other provisions of the Traffic Code apply

Risk warning

Hazardous chemical substances are marked with proper pictograms:



Where hazardous substances are present, be especially cautious and use sufficient Personal Protective Equipment.

Personal Protective

As you stay in designated areas, use sufficient PPE:



Wear working or protective clothes, mandatorily with long sleeves and legs



Use protective headgear



Wear protective glasses sufficient for the danger, securing you against particles or splashing



Wear toe capped safety footwear



Carry a gas mask with a multi-gas absorber (ABEK)

Alarm signals

In the case of a failure, you will be alarmed with:

ALARM!



Voice communication with the information on the type of event and proper procedure

Interrupted sound of the siren for 3 minutes



Cars with sound systems

Procedure in the case of breakdowns

After the alarm is signalled, follow this advice:

1. Leave the contamination line perpendicularly to the wind direction
2. Evacuate to the topmost floor of the nearest building, shut the doors and windows, turn off air conditioning and ventilation systems, call for help
3. If you are driving a car, stop it to not hinder the rescue services, stop the engine but leave the keys in the ignition, carry on as described above
4. In the case of an evacuation order at the Plant, together with its employees, go to the designated Assembly Point; while you are leaving the premises of the plant, give your single-entry pass.
5. If necessary, use your respiratory protective equipment or handkerchiefs and other textiles soaked in water
6. Follow the instructions of the rescue services
7. Listen for the cancellation of the alarm and in case the evacuation is announced, follow hints you are provided



emergency number
71 794 29 98




emergency number
71 794 29 98



emergency number
71 794 29 98



Location plan of PCC GROUP Brzeg Dolny



OFFICES (acc. to the building no.)

- F-8 - PCC MCAA
- F-21 - Locochem, LabMatic
- F-22 - PCC Aparor
- G-1 - LabAnalityka, CWB Partner
- G-2A - PCC Exol
- G-3 - Reception area
- G-5 - Board Office
- G-5A - PCC CP Kosmet
- G-16 - PCC PU
- H-18 - Power Generation Centre
- H-52 - Ecologistics
- L-2 - PCC Autochem
- S-6 - PCC Packaging
- S-8 - PCC Therm
- X-3 - Investment Office, Procurement Office
- CHP - Chempark

MANUFACTURING DEPARTMENTS

- CTP-1 - Chlorine Manufacturing Dept.
- CTP-2 - Causitic Soda Manufacturing Dept.
- CTP-3 - Propylene Oxide Manufacturing Dept.
- CTP-4 - Chlorobenzene and Hydrochloric Acid Manufacturing Dept.
- EC - Combined Heat and Power Generation Centre
- ETE-1 - Ethoxylates Manufacturing Dept. [PCC Exol]
- ETE-1 - Formulations Manufacturing Dept. [PCC Exol]
- ETS-1 - Sulphated Derivatives Manufacturing Dept. I [PCC Exol]
- ETS-2 - Sulphated Derivatives Manufacturing Dept. II [PCC Exol]
- FTT-1 - Phosphorous Derivatives Manufacturing Dept.
- FTT-2 - Flame Retardants Manufacturing Dept.
- KOS - PCC CP Kosmet Manufacturing Dept.
- MCAA - Monochloroacetic Acid Manufacturing Dept. [PCC MCAA]
- PTP - Prepolymers Manufacturing Dept. [PCC PU]
- RTP-3 - Polyesters and Systems Manufacturing Dept. [PCC PU]
- RTP-2 - Rokopols Manufacturing Dept.
- RTP-3 - Polymer Rokopols and Rokryls Manufacturing Dept.
- THERM - Insulation Systems Manufacturing Dept. [PCC Therm]

MISCELLANEOUS

- W - Scales for inter-weighing
- DZ - Plant Dispatcher (tel. 71 794 2441)
- ZSR - ZSR - Plant Rescue Service
- Central Medical Checkpoint
- PCC Intermodal
- ADAMA - offices
- DBI - DB Schenker Rail Spedkol
- Assembly point for evacuation
- Tank trailer wash
- Customs Checkpoint

← Uraz, Wrocław

→ Centre